26-Jun-03

Issue#	Issue	Coordination	Lead Agency
S1	Increase in demand for emergency response services	1	All
General Locatio	n: System wide		
Recommendatio	ns Local agencies will need to make staffing case to elected officials.		
S2	Course of action in short-term for high-crash intersections/segments in study are	0	All
General Locatio	n: High-crash intersections and segments throughout the study area.		
Recommendatio	ns Review signing, striping, access and enforcement until long-term solutions implemented.		
S3	Traffic enforcement	1	All
General Locatio	n: System wide		
Recommendatio	ns Target high problem areas or conduct saturation patrols to increase level of effectiveness and visibility for costs incurred.		
S4	Increase in train speeds, length and weight - impact on crossing safety	1	All
General Locatio	n: Regional		
Recommendatio	ns With change in rail operations, it is important to check crossings in area to make that sight distance and warning signs are present. Crossing consolidation should b emphasized if crossings are duplicated or infrequently used.		
SY1	On-road bicycle facilities (transportation and recreational function)	3	All
General Locatio	n: System wide		
Recommendatio	ns Develop an overall trail and on-road bicycle system. Coordinate connections between recreational and transportation uses.		
CS1	Drivers using Van Brunt Street as a cut-through from West Mankato to the hillto area	2	Blue Earth Count
General Locatio	n: Van Brunt Street at intersection with BEC CSAH 16 (Stoltzman Rd)		
Recommendatio	ns Consider a median on BEC CSAH 16 (Stoltzman Rd) at intersection with Van Bru Street to prevent left turns onto Van Brunt Street (when converted to a two-way street).		

26-Jun-03

Issue#	Issue	Coordination	Lead Agency
CS2	Increased volumes on BEC CSAH 16 (Stoltzman Road), need for widening, pedestrian paths	3	Blue Earth County
General Locatio	n: BEC CSAH 16 (Stoltzman Rd) - from Pleasant St. to the BEC CSAH 90 (South Route)		
Recommendation	ns City and county are working to resolve road width issues; project would then mov forward.		
S10	Red Jacket Trail crossing on Doc Jones Road	1	Blue Earth County
General Locatio	n: Intersection of Red Jacket Trail with Doc Jones Rd.		
Recommendatio	ns Post signage on the Red Jacket Trail and Doc Jones Road. Trim trees near the intersection to improve visibility. Long-term improvements, a box culvert for g separation, can be made when Doc Jones is upgraded.		
S11	Rail crossing safety on BEC CSAH 3	1	Blue Earth County
General Locatio	n: Rail crossing: BEC CSAH 3		
Recommendatio	ns Check appropriateness of warning devices and clear brush to improve visibility of approaching trains.		
S13	Railroad blocks BEC CSAH 12 (Industrial Road)	1	Blue Earth County
General Locatio	n: BEC CSAH 12 (Industrial Park Road) - at intersection with railroad (near scrap dealer)		
Recommendatio	ns BEC to monitor problems. Consider spur realignment to eliminate two crossings		
S14	Limited visibility and speed issues on BEC CSAH 16 (Stoltzman Rd) intersections (in area of Doc Jones Road)	2	Blue Earth County
General Locatio	n: BEC CSAH 16 (Stoltzman Rd) - near Doc Jones Road		
Recommendatio	ns Reconstruct curves to correct superelevation problems and sight problems. Improvements should conform to long-term objectives for BEC CSAH 16 (capac trails/paths).		
S6	Pedestrian safety BEC CSAH 60 (Stadium Road)	3	Blue Earth County
General Locatio	n: Near MSU campus		
Recommendatio	ns As a short-term solution, median treatments and fencing will be installed to prev students from crossing mid-block. Long-term solutions need to be developed and		

26-Jun-03

	Issue	Coordinatio	Lead Agency
S7	MSU students crossing without regard to traffic control devices and designated crossing locations.	3	Blue Earth County
General Location	e: CSAH 60 (Stadium Rd) from Ellis Avenue to BEC CSAH 8 (Monks Ave.)		
Recommendation	s Consolidate access and pedestrian crossings locations. Install median fencing to prevent students from crossing mid-block. Look at long-term pedestrian and parl solutions.		
S8	High speeds on BEC CSAH 90	1	Blue Earth County
General Location	2: BEC CSAH 90 from TH 22 to TH 169		
Recommendation	s BEC CSAH 90 was constructed as a southern bypass to Mankato. As such, it is intended to provide a highlevel of mobility (high-speed) with minimal stops or delays. Consider increased traffic enforcement.		
S 9	High speeds on BEC CSAH 8	2	Blue Earth County
General Location	:: BEC CSAH 8 from 5th St. to BEC CSAH 90		
Recommendation	s Conduct speed study; city is installing sidewalks to reduce level of conflicts.		
SY5	Need to develop better BEC CSAH 60 (Stadium Rd) connection to Victory Dr.	3	Blue Earth County
	Need to develop better BEC CSAH 60 (Stadium Rd) connection to Victory Dr. BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83	3	Blue Earth County
General Location			Blue Earth County
General Location	s: BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83 S Consider alignment that turns BEC CSAH 60 (Stadium Rd) to north to provide 3		Blue Earth County Cities
General Location	a: BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83 S Consider alignment that turns BEC CSAH 60 (Stadium Rd) to north to provide intersection or cross street with BEC CSAH 82 (see the concept in Appendix E). Residential, commercial and industrial developments need to accommodate other modes of transportation.		·
General Location Recommendation O1 General Location	a: BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83 S Consider alignment that turns BEC CSAH 60 (Stadium Rd) to north to provide intersection or cross street with BEC CSAH 82 (see the concept in Appendix E). Residential, commercial and industrial developments need to accommodate other modes of transportation.	1	·
General Location Recommendation O1 General Location	a: BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83 s Consider alignment that turns BEC CSAH 60 (Stadium Rd) to north to provide a intersection or cross street with BEC CSAH 82 (see the concept in Appendix E). Residential, commercial and industrial developments need to accommodate other modes of transportation. s: System wide s Specific criteria should be developed to make sure that other modes of transportation are considered as part of the planning process for approving site plans (pedestrian).	1	·
General Location Recommendation O1 General Location Recommendation	a: BEC CSAH 60 (Stadium Road) - Map Drive to BEC CSAH 83 s Consider alignment that turns BEC CSAH 60 (Stadium Rd) to north to provide a intersection or cross street with BEC CSAH 82 (see the concept in Appendix E). Residential, commercial and industrial developments need to accommodate other modes of transportation. System wide s Specific criteria should be developed to make sure that other modes of transportation are considered as part of the planning process for approving site plans (pedestrian bicycles and transit).	1	Cities

26-Jun-03

	Issue	Coordination	Lead Agency
C2	Continue improvements on remaining segment of 2nd Street	1	City of Mankato
General Locatio	on: 2nd Street from Main Street to Cherry		
Recommendatio	ons Convert the four-lane facility to a three-lane roadway with parking on both sides. This should be a continuation of the improvements that were completed on the Cherry to Warren segment of 2nd Street.		
CS4	Parking on 1st Avenue hinders truck movements	1	City of Mankato
General Locatio	on: 1st Avenue, Mankato		
Recommendatio	ons Mankato could consider parking restrictions near entrances along 1st Avenue.		
CS5	High number of left turns into MSU parking lot causing backups	1	City of Mankato
General Locatio	on: Birchwood Street from Warren Street to Ellis Avenue		
Recommendatio	ons Restripe Birchwood Street from two-lane facility to a three-lane roadway with a		
	center left turn facility, eliminating parking on both sides.		
CS6	Parking and access on Riverfront Drive between Plum Street and Vine Street	1	City of Mankato
		1	City of Mankato
General Locatio	Parking and access on Riverfront Drive between Plum Street and Vine Street		City of Mankato
General Locatio	Parking and access on Riverfront Drive between Plum Street and Vine Street on: Riverfront Drive between Plum Street and Vine Street ons Undertake a study to determine the impacts of removing on-street parking and acclosures for driveways between Lime and Vine Street. Once safety and mobility benefits are determined, they should be evaluated against impacts to businesses and		City of Mankato
General Locatio Recommendatio J2	Parking and access on Riverfront Drive between Plum Street and Vine Street on: Riverfront Drive between Plum Street and Vine Street ons Undertake a study to determine the impacts of removing on-street parking and acclosures for driveways between Lime and Vine Street. Once safety and mobility benefits are determined, they should be evaluated against impacts to businesses an residents.		
General Locatio Recommendatio J2 General Locatio	Parking and access on Riverfront Drive between Plum Street and Vine Street on: Riverfront Drive between Plum Street and Vine Street ons Undertake a study to determine the impacts of removing on-street parking and acclosures for driveways between Lime and Vine Street. Once safety and mobility benefits are determined, they should be evaluated against impacts to businesses an residents. Jurisdictional responsibility of Madison Avenue	3	
General Locatio Recommendatio J2 General Locatio	Parking and access on Riverfront Drive between Plum Street and Vine Street on: Riverfront Drive between Plum Street and Vine Street ons Undertake a study to determine the impacts of removing on-street parking and acclosures for driveways between Lime and Vine Street. Once safety and mobility benefits are determined, they should be evaluated against impacts to businesses an residents. Jurisdictional responsibility of Madison Avenue on: Madison Avenue - Riverfront Drive to TH 22 ons Route should be considered for transfer to Blue Earth County jurisdiction. This reprovides continuity from the rural area to the central city and provides for highe	3	
General Location Recommendation J2 General Location Recommendation O4	Parking and access on Riverfront Drive between Plum Street and Vine Street on: Riverfront Drive between Plum Street and Vine Street ons Undertake a study to determine the impacts of removing on-street parking and acclosures for driveways between Lime and Vine Street. Once safety and mobility benefits are determined, they should be evaluated against impacts to businesses an residents. Jurisdictional responsibility of Madison Avenue on: Madison Avenue - Riverfront Drive to TH 22 ons Route should be considered for transfer to Blue Earth County jurisdiction. This reprovides continuity from the rural area to the central city and provides for highe mobility lower land access functions.	3	City of Mankato

26-Jun-03

	Issue	Coordination	Lead Agency
O6	Lamm Street access to Riverfront Drive	1	City of Mankato
eneral Locatio	on: Lamm Street - at potential intersection with Riverfront Drive		
ecommendatio	ons A traffic study should be completed to identify impacts to traffic volumes on Riverfront Drive, as well as impacts to access spacing guidelines. Consider comprehensive access management study for Riverfront Drive.		
O7	Extension of sewer service	3	City of Mankato
General Locatio	on: Lake Washington area		
Recommendatio	ons Extension of sewer service should be pursued to address environmental concerns; to encourage sprawl in rural areas.		
S18	Ability of emergency response vehicles to get to crash sites	2	City of Mankato
General Locatio	on: TH 22, Madison Avenue near the mall		
Recommendatio	ons Install emergency vehicle preemption (EVP) technology on city and county cont		
	traffic signals. Support Adams Street and other alternate route options.		
S19	traffic signals. Support Adams Street and other alternate route options. Crosswalk at Marsh St. and Division St. is in wrong location	1	City of Mankato
		1	City of Mankato
General Locatio	Crosswalk at Marsh St. and Division St. is in wrong location	1	City of Mankato
General Locatio	Crosswalk at Marsh St. and Division St. is in wrong location on: Intersection of Marsh St. and Division St. ons Work with Bethany College to identify a location that will better serve students. Lack of sidewalks on both sides of the road on four-lane streets in residential area	2	
General Location Recommendation S20	Crosswalk at Marsh St. and Division St. is in wrong location on: Intersection of Marsh St. and Division St. ons Work with Bethany College to identify a location that will better serve students.		
General Location Recommendation S20 General Location	Crosswalk at Marsh St. and Division St. is in wrong location on: Intersection of Marsh St. and Division St. ons Work with Bethany College to identify a location that will better serve students. Lack of sidewalks on both sides of the road on four-lane streets in residential area (Mankato)	2	
General Location Recommendation S20 General Location	Crosswalk at Marsh St. and Division St. is in wrong location on: Intersection of Marsh St. and Division St. ons Work with Bethany College to identify a location that will better serve students. Lack of sidewalks on both sides of the road on four-lane streets in residential area (Mankato) on: System wide ons Identify locations where four-lane facilities are located. In areas that are develop include sidewalks or trails on both sides of the road where existing or projected	2	City of Mankato
General Location Recommendation S20 General Location Recommendation	Crosswalk at Marsh St. and Division St. is in wrong location on: Intersection of Marsh St. and Division St. ons Work with Bethany College to identify a location that will better serve students. Lack of sidewalks on both sides of the road on four-lane streets in residential area (Mankato) on: System wide ons Identify locations where four-lane facilities are located. In areas that are develop include sidewalks or trails on both sides of the road where existing or projected volumes exceed 10,000 vehicles per day.	2	City of Mankato City of Mankato

26-Jun-03

Issue#	Issue	Coordination	Lead Agency
S23	Intersection safety Raintree Road and River Hills Mall entrance	1	City of Mankato
General Locatio	on: Intersection of Raintree Rd. and River Hills Mall entrance		
Recommendatio	ns Consider moving/shifting mall entrance and other access point further north/wes gain better intersection spacing and stacking room.		
S26	Intersection safety Warren Street and Riverfront Drive	1	City of Mankato
General Locatio	on: Warren Street and Riverfront Drive		
Recommendatio	ans Review crash reports to determine if there are known crash causes that can be addressed (i.e., visibility issues, geometric issues, signal timing, etc.).		
S27	Segment safety Van Brunt Street	3	City of Mankato
General Locatio	on: Van Brunt Street from BEC CSAH 16 (Stoltzman Rd) to Center Street		
Recommendatio	Ins Consider changing this roadway from a one-way to a two-way to create a friction movement, which should calm traffic. Consider removing Van Brunt from the St Aid system.		
S28	Segment safety Pleasant Street	1	City of Mankato
General Locatio	on: Pleasant Street from BEC CSAH 16 (Stoltzman Rd) to Highland Street		
Recommendatio	ons Convert this roadway from a one-way to a two-way facility. Parking will need to removed.		
S29	Segment safety 2nd Street	1	City of Mankato
General Locatio	on: 2nd St. from Cherry to Warren		
Recommendatio	ons Monitor the number, type and severity of crashes along this corridor to determin there is a safety problem and identify potential solutions.		
	Segment safety Balcerzak Drive	1	City of Mankato
S30			
	on: Balcerzak Drive - from Monks Avenue to Warren Street		

26-Jun-03

Issue#	Issue	Coordination	Lead Agency
S32	Segment safety Commerce Drive	1	City of North Mankato
General Locatio	on: Commerce Drive- from Nicollet County CSAH 13 to Lor Ray Drive		
Recommendatio	ns Review corridor to determine potential for consolidating access.		
S 33	Segment safety Center Street	1	City of North Mankato
General Locatio	on: Center Street - Belgrade Avenue to TH 169		
Recommendatio	ens This segment is a short segment, therefore the crash rates are exaggerated. Ther were seven crashes in a 3 year period on this segment. The city should monitor future crashes.		
S37	Need to improve signage near BEC CSAH 33 and TH 169	1	Mn/DOT
General Locatio	on: TH 169 and BEC CSAH 33 intersection.		
Recommendatio	ins Review signing and striping at this location.		
SY10	Limited room for bikeway facility on Bottom Road (old Nicollet CSAH 41)	1	Nicollet County
General Locatio	on: Nicollet CSAH 41 from junction (north/south segment 41) to Nicollet CSAH 23		
Recommendatio	ons Pursue grant money from the DNR or other agencies for a separate pedestrian/bicycle facility at Minnemishiona Falls.		
S38	Mankato West students illegally crossing the road	1	School District
General Locatio	on: Riverfront Dr. from BEC CSAH 16 (Stoltzman Rd.) to Popular Ave.		
Recommendatio	ons Depending on severity of problem, consider using crossing guards along intersections with Riverfront Dr. before school, during lunch and after school; provide information at homeroom on proper crossing area/procedures.		
O16	Growth in South Bend Township	3	South Bend Township
General Locatio	on: In growth areas near the City of Mankato		
Recommendatio	ons South Bend should work with Blue Earth County and Mankato to plan for long-to- growth. If appropriate, an annexation agreement should be developed. Explore j representation on planning commissions that review and approve development in growth areas.		